


FIG. 1

(a)



(b)





FIG. 2

8A } INSPECTION LIGHT BEAM
8B }



7 CHIPPING DEFECT
4 PHASE-180° SHIFTER PORTION
5 PHASE-0° PORTION
6 PROTRUSION DEFECT

FIG. 3




FIG. 4




FIG. 5




FIG. 6

